

SB 4550-05-A Service Bulletin SA4550 Primary Attitude Display

Date: March 14, 2011

Regarding: SA4550 Software Version 1.07 Release

Reason

Sandel has received field reports of blanking of some SA4550 displays. This software release corrects this problem.

Applicability

This SB applies to all SA4550 installations.

Compliance

Mandatory: To be performed at next scheduled aircraft service or within 25 hours of blanking occurrence.

Description

The SA4550 display may blank for approximately 8 seconds and then resume normal operation. At no time is attitude incorrectly displayed. This was caused by an improper threshold on an internal safety system.

The SB 4550-05 related files including the software update, software load utility and instructions can be accessed on the Sandel website at:

www.sandel.com/SA4550_sup_sb.php [case-sensitive]

Or you can contact Sandel Product Support at (760)727-4900 selection "2"

Warranty Reimbursement

1 hour.

Manpower

1 hour

Approval

This modification does not affect the original approval.

Contact Sandel for details if needed.

Identification

No change

Testing

None required.

Related Documentation

82010-PGERR Rev D2

Pilot's Guide Errata

END