

SIL 3500-21 Service Information Letter SN3500 Primary Navigation Display

Date: October 8, 2014

Regarding: SN3500 Primary Navigation Display, Software Release A4.07

SIL Revision: A (Initial)

Reason

This Service Information Letter is informational only. No action is required.

An issue affecting USB communication during the SN3500 production process was reported. Units presently in service are not affected.

Applicability

Applies to Sandel part number SN3500-xxx and SN3500-xxxx with MOD A (Serial numbers 5-4500 and above)

Description

SN3500 software was revised to version A4.07 for improved manufacturing yield and incorporated into production beginning with serial number 5-4584

Compliance

Optional for units presently in service with software version A4.06 if fleet uniformity is desired. Operation is unchanged.

Warranty Reimbursement

None

Manpower

1 hour

Approval

This modification does not affect the original approval. Contact Sandel for details if needed.

Identification

No change

Testing

None

SANDEL®

Documentation

82005-PG-ERR-M3

Pilot's Guide Errata

END