SANDEL®

SIL SG102-11   Service Information Letter
SG102 AHRS

Date: May 6, 2015
Regarding: SG102 AHRS Software Release 1.62
SIL Revision: A (Initial)

Reason

Release of new software version 1.62

Applicability

Sandel Model SG102 - part number SG102-X00 with MOD 2
Sandel Model SG102/D - part number SG102-X50

Description

Software version 1.62 has the following changes:

- Improves performance during low-bank turns.

- Corrects the slaving meter output on the SG102 P2 connector for proper indication on King KA 51A/B slaving accessories.

SG102 MOD 2 and SG102/D units with software version 1.61 can be updated to version 1.62 in the field.

SG102 MOD 2 and SG102/D with software version 1.5X must be returned to Sandel if the software update is desired.

SIL SG102-11 related files can be accessed on the Sandel website at: www.sandel.com/sg102/sg102-support

Note regarding spares: SG102 software version 1.62 is backward compatible with prior field calibrations in existing installations with SG102 software version 1.26 or later. If it is decided to re-calibrate the system then field calibration software version 2.80 or later must be used.

Compliance

Optional

Warranty Reimbursement

N/A

Manpower

1 hour

SANDEL®

Approval

This modification does not affect the original approval.

Identification

No change

Testing

None

Related Documentation

82011-IM Rev. J (or later)	Installation Manual (No content changed)
82011-PGERR Rev. E3	Pilots Guide Errata
82011-ICUG Rev. G	Installation/Calibration Utility User Guide

END