

**Effectivity, Errata and Revision History**

82010-PG-ERR Revision D2

Date: March 01, 2011  
Revision: D2  
Applies to: SA4550 Software 1.07  
SA4550 Pilot's Guide 82010-PG Revision D

With the exception of the superseding information contained in this section, operation of the SA4550 is as described in the SA4550 Pilot's Guide referenced above.

Revision	Date	Comments
D2	03/01/2011	Release for 1.07 Software
D1	11/11/2008	Release for 1.06 Software
D	7/15/2008	Release for 1.05 Software Page 2-22: New annun. added. Page 2-23: MDA annun. added. Page 2-25: RNAV annun..added. Page 3-1: New part number added. Chapt 5.: Added abbreviations.
C	02/27/2008	Release for 1.04 software, Update page 2-8 "Function Not Installed" message. Update physical characteristics (chapter 3)
B2	10/17/2007	Page x: Effectivity updated for Software 1.03. No operational changes.
B1	08/22/2007	Page x: Effectivity updated for Software 1.02; Document number reference added; Errata updated for incorrect page reference. No operational changes.
B	06/18/2007	New Format
A	05/07/2007	Initial Release

No errata applicable to this release.

**Pilots Guide, document number 82010-PG**

**Revision Number D2**

(Consists of 2 pages: one instruction page and one revision page)

**Instructions:**

Insert D2 update adjacent to page x and line out existing Revision D1 page x.