

## **SIL 3500-16      Service Information Letter SN3500 Primary Navigation Display**

---

Date:            30-NOV-2010

Regarding:    SN3500 Primary Navigation Display, Software Release 4.03

SIL Revision: A (initial)

### **Reason**

Availability of new SN3500 Software Release 4.03

### **Applicability**

Applies to Sandel part number SN3500-xxx and SN3500-xxxx

### **Description**

This new release of software provides the following enhancements:

- Improved of TACAN Receiver Self Test Display.  
*[Note: The TACAN display option software key (p/n 90143-TCN) is subject to the licensing jurisdiction of the Department of State in accordance with the International Traffic in Arms Regulations (ITAR) (22 CFR 120 – 130). It may not be exported (sent, transferred, disclosed or otherwise released to a foreign person) without a license issued by DDTC.]*
- Improved External Brightness Trim Setting.
- Increased resolution of Heading and Course Datum output signals.

SIL 3500-16 related files including the software update, software load utility and instructions can be accessed on the Sandel website at:

[www.sandel.com/SN3500\\_EHSI\\_sup\\_sb.php](http://www.sandel.com/SN3500_EHSI_sup_sb.php) [case-sensitive]

- or -

contact Sandel Product Support at (760)727-4900 selection "2"

# SANDEL®

## **Compliance**

Optional

## **Warranty Reimbursement**

None

## **Manpower**

1 hour

## **Approval**

This modification does not affect the original approval.  
Contact Sandel for details if needed.

## **Identification**

No change

## **Testing**

None

## **Documentation**

82005-IM Rev. K	Installation Manual
82005-PG Rev. K1	Pilot's Guide
82005-PGSUP Rev.	CPilots Guide Supplement