

**SIL 4550-06      Service Information Letter**  
**SA4550 Primary Attitude Display**

---

Date:            June 13, 2013  
Regarding:    SA4550 MOD 3  
SIL Revision: A – Initial Notification

**Reason**

Availability of new SA4550 hardware mod to prevent excess vibration of the slip/skid ball display which has been observed in some installations.

**Applicability**

Applies to all variants of the SA4550 Sandel part number SA4550-xxx software version 1.01 and later.

**Description**

This new hardware mod provides the following change:

- Reduces slip skid ball display susceptibility to vibration seen in some installations.

Contact Sandel Product Support at (760)727-4900 to schedule this mod for your unit. This mod will be performed at no charge.

**Compliance**

As required.

**Warranty**

None.

**Documentation**

None

**End**