


DATE	REV	COMMENTS
10/23/00	G	INITIAL RELEASE
04/03/01	G1	A/R 360 PAGE COUNT
10/04/02	G2	A/R 573 PAGE COUNT

COMPUTER CONTROLLED DRAWING
DO NOT REVISE MANUALLY



DOES NOT SHOW NAV 1, NAV 2, GPS 1, GPS 2, DME OR STORMSCOPE INTERFACE. PLEASE SEE SPECIFIC DRAWINGS FOR INTERCONNECT MAYBE USED AS TEMPLATE+

NOTES:

1. THESE LOAD RESISTORS ARE REQUIRED FOR PS ENGINEERING MARKER RECEIVERS. RECOMMENDED FOR OTHER RECEIVERS TO PREVENT FAILURE OF THE SN3308 INDICATION IF THE ASSOCIATED MARKER LIGHT BULB FAILS.
2. SELECT THE APPROPRIATE MARKER BEACON RECEIVER ON THE SN3308 MARKER BEACON INSTALLATION PAGE. IF SPECIFIC RECEIVER NOT SHOWN USE KMA-24 SETTING.

SANDEL		Vista, Ca.
Category SN3308 INSTALLATION DRAWING		
Title MID-CONTINENT SIMPLIFIED BLOCK DIAGRAM		
Size B	Document Number 90106-10	Rev G2
Create: Wednesday, October 18, 2000		Mod: Thursday, September 25, 2003
Sheet 4		