

SB 3500-11 Service Bulletin

Date: 08-DEC-2008

Regarding: SN3500 Primary Navigation Display Software Version 3.06 Release

Revision: A, Initial Release

Reason

Automatic Navigation source selection syncing with Garmin receivers is unavailable in SN3500 Software version 3.04 or 3.05.

Applicability

Applies to Sandel part numbers SN3500-xxx and SN3500-xxxx with software version 3.04 or 3.05, and installed with a Garmin GNS 400(W)/500(W) series receivers. Installations with Garmin GNS 480 are not affected.

Description

This new release of software restores a previous capability to auto synchronize the NAV source selection between the SN3500 and Garmin GNS receivers.

SB 3500-11 related files including the software update, software load utility and instructions can be accessed on the Sandel website at:

www.sandel.com/SN3500_EHSI_sup_sb.php [case-sensitive]

or you can contact Sandel Product Support at (760)727-4900 selection "2"

Compliance

Optional

Warranty Reimbursement

None

Manpower

1 hour

Approval

This modification does not affect the original approval.

Identification

No change

Testing

Refer to ground test section of SN3500 Primary Navigation Display Installation Manual, Document 82005-IM Revision F.

Documentation

82005-IM Rev. F Installation Manual

82005-PG Rev. H1 Pilot's Guide