

SIL 4550-01 SA4550 Primary Attitude Display Service Information Letter

Date: August 30, 2007
Regarding: SA4550 1.02 Software Release

Reason

Availability of new SA4550 Software to correct radar altimeter pin outs and enhance the maintenance pages text.

Applicability

Applies to Sandel part number SA4550-xxx with 1.01 software.

Description

This new release of software provides the following changes:

- Corrects pin out for radar altimeter type selection
- Maintenance page text enhancements

In accordance with the SA4550 Component Maintenance Manual, document number 82010-0133, revision A, SIL 4550-01 related files including the software and update utility can be accessed on the Sandel website at:

www.sandel.com/SA4550_sup_sb.php [case-sensitive]

or you can contact Sandel Product Support at (760)727-4900 selection "2"

Update the existing Pilot's Guide, document number 82010-PG revision B with the updated "Effectivity, Errata and Revision History" page, document number 82010-ERR revision B1.

Update the existing installation manual, document number 82010-IM revision B to B1 with document number 82010-IM-RN revision B1.

Compliance

Mandatory for SA4550-1xx part numbers; recommended for SA4550-0xx part numbers.

SANDEL®

Warranty

None

Documentation

82010-PG-ERR Revision B1 Pilot's Guide Effectivity page
82010-IM-RN-B1 Installation Manual Revision Number B1

End