

SB 3400H-07 Service Bulletin (Mandatory) ST3400H HeliTAWS™

Date: February 3, 2016
Regarding: ST3400H HeliTAWS Database Release
SIL Revision: A – Initial Notification

Reason

An internal audit of the ST3400H obstacle database discovered some obstacles were at incorrect heights. This database release contains corrected obstacle information.

Applicability

Applies to Sandel ST3400H units operated outside of the USA with obstacle data dated prior to 01JAN16. This does not apply to data within the USA.

Description

A new database update is available for the ST3400H. Following the update the unit will reflect the following database dates:

Terrain Rev:	10DEC09
Obstacle Rev:	01JAN16
Airport Rev:	07JAN16
Overlay Rev:	01JAN13

Compliance

Mandatory for ST3400H units operated outside of the USA as soon as practical.

For questions or to establish a database subscription please contact Sandel Product Support at support@sandel.com with the serial numbers of the affected units.

Warranty

Database update will be provided at no charge for units with a current database subscription

Documentation

Not applicable

END